

Appendix 1 – HRFC floodlighting improvement project



Looking north-west across pitch No. 2, with existing floodlight system



Looking south-east across pitch No. 2, with existing floodlight system

Existing column 1



Existing column 2



Existing column 3



Existing column 4



Existing column 5



Existing column 6



Proposed cabinet location just beyond 5 bar gate

