

The existing bungalow is incredibly energy inefficient with little potential for improvement in terms of any refurbishment. I've not ever seen such a low existing or potential EPC rating. Please see attached.

