

1.80

20.95

OAK FRAMED BAY WINDOW

EXISTING HISTORIC OAK FRAME

REPAIR/REPLACED IN NEW OAK.

BAY INDICATES AREAS OF DECAY.

INDICATES MORTIS & TENON JOINTS
INDICATES BUTTER AND NAILER JOINTS.

17.01

No window frame

15.73

Roof under construction

BRICK STRING COURSE

Brick

NEW WINDOW.
94X145.

* SOX 100 *

Brick

BRICK STRING COURSE

16.32

94X145

14.85

* 94X145 *
SOX 100

SOX 100

13.95

FLOOR GIRING BEAM
BADLY DECAYED.

94X145

Brick

Brick

11.68

94X145

Brick

12.01

Alt. GOLF LTP.

14/05/2019

THE MANOR. PO9 3JT

FRAME AS EXISTING



AH. BOCC LTD.
 14/05/2019
 THE MANOR, POBSI
 FRAME AS REPAIRED