

A bright dining room with a wooden table, chairs, and a bench. The room features white walls, a large window with a view of greenery, and a small table near the window. A framed picture hangs on the wall.

A photograph of a room undergoing renovation. The walls are made of exposed brick and plaster, with some areas showing signs of decay. A white door is visible on the left. A blue tarp is draped over a pile of debris in the center. Construction materials, including wooden planks and beams, are scattered on the floor. Red handwritten markings are visible on the wall.

A photograph of a severely damaged interior wall. The wall is composed of brick and plaster, with significant portions of the plaster missing, revealing the underlying brickwork and structural elements. A wooden beam or pole is leaning against the wall, and a white door is visible on the right side.

A close-up photograph of a corner where a brick wall meets a wooden structure. The wall is made of red and white bricks, some of which are missing or crumbling. A large, jagged crack runs diagonally across the corner, exposing the wooden lath underneath. The lath is dark and appears to be made of multiple layers of wood. The overall condition is one of significant structural damage and decay.

Refer to Dwg MHB-02 for notes



Murphy Associates
Planning.Urban Design.Conservation