

Joinery Details

Front

Ground floor

No horns to any windows

Windows to porch

Multi paned no opening lights

First Floor front

Centre to staircase - no horns

No horns to any windows.

Attic

No horns to any windows

Rear

Ground Floor

Rising Bay - with horns to top and bottom tripartite sash.

Single Storey Bay - no horns

First Floor

Rising Bay - with horns to top and bottom tripartite sash.

Gabled wings - no horns

Attic

Rising Bay - No horns - flush window!

No horns to other windows.

Side north

Ground floor - to east of stack, mutli paned, not a sash. Does not need replacing.

First Floor - with horns to sash bottom to east of stack. Does not need to be replaced. Needs new cill.

First Floor window to west side of stack only needs repairing. It is not a sash. Has one opening light

Side South

1 window to first floor - no horns.



Front elevation




Part Rear (East) Part Side (North)




Rear (East)


Joinery Profiles with dimensions (mm)




Cross Section to Bottom Rail




Cross Section Frame Uprights



Lower Sash with Puttied Bead, Single Glazing



Base



Glazing Bar