

## Photo Survey

### North Elevation

This elevation was originally open sided as a cart shed but was bricked up in approximately 1960 to allow more secure storage of farm goods. The ventilated door is secure but left as a wire mesh gate to allow airflow to assist the fan in drying the crops stored in the adjacent barn.



### West Elevation

This elevation boasts a well built flint wall. It has an outlet from the valley which is in need of repair. There is a stable door to the right. There is also a drain for rainwater.



### South Elevation

The elevation has 3 windows 1 large and 2 smaller. It has a large stable door. This elevation faces a courtyard area.



### West Elevation

The west elevation is currently a 9 inch block wall of a grain store. It is intended to remove the section outlined in red which will mean the dairy will be fully detached from any building and will allow a court yard area as the wall to the north will be retained.



The building currently has electricity and water already installed. It will be necessary to install a new sewer pipe however there is main drainage easily accessible in the yard so major excavations will not be required.