

APP/22/00476 and APP/22/00475

From: [Redacted text]
Sent: 01 July 2022 22:05
To: Donophy, Selina
Subject:

CAUTION: This email came from outside of the council - only open links and attachments that you're expecting.

Dear Selina,

The existing chimney stack would appear to be solid masonry construction from the Little Seafeld side with a render. It is below gutter level. To extend it up would produce yet another harmful artefact to a listed wall evidence of previous harm still evident (image 2)with protruding stainless external flue. The outlook from the listed Little Seafeld hugely impacted again. The bricks to the greenhouse are a mix but all are no more than 5cm high and 20cm in length and many smaller. (Image 3)

The suggested heritage bricks bear no resemblance to those in the current construction and would be very much an unsightly column of new brick add-on.

I

Image 3

Image 2

As pointed out in previous correspondence a drawing of Sea Field Lodge shown in the Helyer Davies Heritage statement is insufficient to inform plans and materials and the greenhouse has been altered considerably when rebuilt in the early 19th century in Mughal style.

A chimney at the current height does not conform to building regulations and it cannot be extended up because there is no evidence to inform this.