

Sent: 26 June 2022 10:43

To: Donophy, Selina; McMurray, Rachael

Subject: APP/22/00475

CAUTION: This email came from outside of the council - only open links and attachments that you're expecting.

Dear Selena and Rachael,

Please may I add the following images to my comment which I submitted yesterday.

The structure which is being called a chimney/buttress does not look brick like from the outside. It has a stucco render. I had always assumed it was something to do with the Smithy/Farm evidence can be seen on the Little Seafeld side. It has been at this height below gutter level with a fabric top certainly since 2000.

Another point reinforcing the invalidity of using drawings as a template for construction and materials is it would appear that the roof of the greenhouse has been raised. The apex now is not as low as in the drawings. The materials in the drawings are totally different to the present construction...



