

How to use plan

More detailed guidance on each Site Guidance Note (SGN) can be found in a printed hard copy compilation of all the SGNs, Manual for Managing Trees On Development Sites version 2.1, issued to the Site Manager at the pre-commencement site meeting. Note: This should be retained on site throughout the duration of works. Additionally, an electronic pdf compilation of all the SGNs, was submitted with this drawing to the local planning authority and the client. Alternatively, a pdf of each SGN can be downloaded by:

1. clicking the image links in the electronic pdf version of this plan;
2. holding a mobile phone QR (Quick Response) code reader over the QR code in the paper version of this plan; or
3. visiting our website at <https://www.barrelltreecare.co.uk/resources/technical-guidance>

Tree protection plan

Location of trees, categorisation & protection/management proposals

Southleigh Park House, Quantel Snell, Eastleigh Road, Havant, Hampshire, PO9 2PE

Barrell Plan Ref: 20122-SchemeB Renumbering


barrell
TREE CONSULTANCY

Permission is granted to scale from this drawing for Local Authority Planning Approval purposes relating to tree protection measures only. Where applicable this drawing is to be read in conjunction with the arboricultural report. This drawing is the copyright of Barrell Tree Consultancy 2021. This drawing to be reproduced in colour only.

www.barrelltreecare.co.uk

SGN 1 Monitoring tree protection

- Always:**
- ✓ have a pre-commencement meeting with the tree consultant before
 - ✓ use the tree consultant to regularly check that protection remains fit for purpose
 - ✓ use the tree consultant to supervise work in RPAs
 - ✓ keep a written report of supervision




SGN 2 Fencing protected trees

- Always:**
- ✓ install protection before development starts
 - ✓ make sure protection is fit for purpose, i.e. it prevents damage to trees and soil
 - ✓ keep protection in place until there is no risk to trees
 - ✓ get written permission to move or remove any protection



SGN 3 Ground protection

- Always:**
- ✓ install protection before development starts
 - ✓ make sure protection is fit for purpose, i.e. it prevents damage to trees and soil
 - ✓ keep protection in place until there is no risk to trees
 - ✓ get written permission to move or remove any protection



SGN 4 Pollution control

- Always:**
- ✓ keep toxic products away from RPAs



SGN 5 Site cranes & piling rigs

- Always:**
- ✓ use the tree consultant to supervise work with cranes and piling rigs in RPAs



SGN 6 Height restrictions

- Always:**
- ✓ prevent the access of vehicles into controlled areas taller than the critical height




SGN 7 Excavating in RPAs

- Always:**
- ✓ use the tree consultant to supervise work in RPAs
 - ✓ use hand tools to dig in RPAs
 - ✓ protect exposed roots from sunlight and drying out



SGN 8 Removing surfacing and structures in RPAs

- Always:**
- ✓ have a pre-commencement meeting with the tree consultant before development starts
 - ✓ use the tree consultant to supervise work in RPAs
 - ✓ minimise damage to roots and disturbance to soil in RPAs
 - ✓ remove excavation when installing or replacing surfacing in RPAs



SGN 9 Installing/upgrading surfacing in RPAs

- Always:**
- ✓ have a pre-commencement meeting with the tree consultant before development starts
 - ✓ use the tree consultant to supervise work in RPAs
 - ✓ minimise damage to roots and disturbance to soil in RPAs
 - ✓ remove excavation when installing or replacing surfacing in RPAs




SGN 10 Installing structures in RPAs

- Always:**
- ✓ use the tree consultant to supervise work in RPAs
 - ✓ install any structure over RPAs down to at least 600mm
 - ✓ protect RPAs from contamination from poured wet concrete




SGN 11 Installing services in RPAs

- Always:**
- ✓ use the tree consultant to supervise work in RPAs
 - ✓ select the least damaging option when installing services, to prioritise tree health, over broken trench over continuous trench
 - ✓ hand dig trenches if trenchless is not feasible



SGN 12 Landscaping in RPAs

- Always:**
- ✓ use the tree consultant to supervise work in RPAs
 - ✓ avoid raising ground levels within 1m of the trunk of retained trees



Tree No.	Species	Category	Notes	Tree Works	RPA
A2	Washed trees			Carry out safety check and if over 3.0-4.0m in as necessary.	
T891	Magrota	B	Severely imbalanced	Reduce and shape by 2	5.8
T892	Oak	A	Some crown defects		13.8
T893	Birch	C	Severe decay in one stem at 0.5 m	Remove decayed stem	2.5
T895	Birch	C	Ash dieback disease, weak union		3.5
T896	Ash	A	Severely imbalanced		4.8
T897	Birch	C	Severely imbalanced		4.8
T898	Birch	C	2 stems from ground level, weak		5.7
T900	Oak	A	Multiple defects in crown		15.0
T901	Yew	B	Growing on an island		2.5
T902	Yew	B	Growing on an island		4.8
T903	Birch	C	Group of tall thin trees growing on an island		1.8
T904	Yew	C	Suppressed		3.6
T905	Giant willow	C	Severely imbalanced stems from weak basal unions	Call for management	4.4
T906	Portuguese laurel	C	Tall, thin, imbalanced		3.6
T907	Portuguese laurel	C	Multiple stems from ground level with weak unions, some severely imbalanced		3.0
T908	Oak	C	Severely imbalanced		6.5
T909	Portuguese laurel	C	Severe storm damage		3.6
T910	Portuguese laurel	C	Poor form		3.0
T911	Ash	C	Ash dieback, severely imbalanced		8.5
T912	Ash	B	Early signs of ash dieback	Call for development	5.8
T913	Portuguese laurel	C	Severe storm defects	Call for development	3.0
T914	Giant willow	C	Decaying weak union in stem	Call for development	4.8
T915	Giant willow	C	Ash dieback, imbalanced	Call for development	3.0
T916	Ash	C	Ash dieback, imbalanced	Call for development	3.6
T917	Ash	C	Ash dieback	Call for development	3.6
T918	Ash	C	Severe defects in crown and ash dieback	Call for development	4.0
T919	Oak	C	Severely imbalanced over pond	Call for development	6.6
T920	Ash	C	Tall thin form, RPA modified by wall	Call for development	3.0
T921	Ash	C	Tall thin form, RPA modified by wall	Call for development	3.6
T922	Ash	C	Tall thin form, RPA modified by wall	Call for development	3.0
T923	Portuguese laurel	C	Severe decay in stem	Call for development	6.0
T924	Oak	C	Tall thin form, ash dieback	Call for development	6.5
T925	Oak	B	Part of group	Call for development	4.8
T926	Ash	B	Part of group	Call for development	4.8
T927	Beech	C	Part of group	Call for development	3.6
T928	Scot pine	B	Part of group	Call for development	15.0
T929	Coastal reedbed	A	5 stems (65, 65, 70, 50, 40)	Call for development	5.8
T930	Holly	B	4 stems (22, 20, 20, 30)	Call for development	5.8
T931	Laurel	C	Poorly formed overgrown shrubs	Call for development	3.0
T932	Portuguese laurel	C	Tall, thin, closely grown trees, poorly formed, some partially fallen	Call for development	3.0
T933	Oak	B	Call for development	Call for development	8.0
T934	Leyland cypress	C	6 closely grown stems, all severely imbalanced	Call for development	4.2
T935	Oak	C	Slightly imbalanced	Call for development	4.2
T936	Ash	C	Ash dieback	Call for development	2.4
T937	Holly chestnut	C	Tall thin form, suppressed	Call for development	2.4
T938	Cherry	B	Tall thin form, suppressed	Call for development	8.0
T939	Cherry	B	Some stem defects	Call for development	2.4
T940	Birch	C	Tall thin form	Call for development	2.9
T941	Ash	C	Ash dieback	Call for development	3.6
T942	Ash	C	Ash dieback	Call for development	3.6
T943	Ash	C	Ash to ash dieback	Call for development	3.0
T944	Ash	C	Ash dieback	Call for development	3.0
T945	Holly	C	Tall thin form	Call for development	3.6
T946	Cherry	C	Tall thin form	Call for development	1.8
T947	Holly	C	Severe basal damage	Call for development	3.0
T948	Ash	C	Ash dieback	Call for development	2.4
T949	Birch	C	Tall thin form	Call for development	3.0
T950	Birch	C	Tall thin form	Call for development	2.4
T951	Birch	C	Tall thin form	Call for development	3.0
T952	Birch	C	Tall thin form	Call for development	2.4
T953	Birch	C	Tall thin form	Call for development	3.0
T954	Birch	C	Tall thin form	Call for development	3.0
T955	Birch	C	Tall thin form	Call for development	3.0
T956	Birch	C	Tall thin form	Call for development	3.0
T957	Birch	C	Tall thin form	Call for development	3.0
T958	Birch	C	Tall thin form	Call for development	3.0
T959	Birch	C	Tall thin form	Call for development	3.0
T960	Birch	C	Tall thin form	Call for development	3.0
T961	Birch	C	Tall thin form	Call for development	3.0
T962	Birch	C	Tall thin form	Call for development	3.0
T963	Birch	C	Tall thin form	Call for development	3.0
T964	Birch	C	Tall thin form	Call for development	3.0
T965	Birch	C	Tall thin form	Call for development	3.0
T966	Birch	C	Tall thin form	Call for development	3.0
T967	Birch	C	Tall thin form	Call for development	3.0
T968	Birch	C	Tall thin form	Call for development	3.0
T969	Birch	C	Tall thin form	Call for development	3.0
T970	Birch	C	Tall thin form	Call for development	3.0
T971	Birch	C	Tall thin form	Call for development	3.0
T972	Birch	C	Tall thin form	Call for development	3.0
T973	Birch	C	Tall thin form	Call for development	3.0
T974	Birch	C	Tall thin form	Call for development	3.0
T975	Birch	C	Tall thin form	Call for development	3.0
T976	Birch	C	Tall thin form	Call for development	3.0
T977	Birch	C	Tall thin form	Call for development	3.0
T978	Birch	C	Tall thin form	Call for development	3.0
T979	Birch	C	Tall thin form	Call for development	3.0
T980	Birch	C	Tall thin form	Call for development	3.0
T981	Birch	C	Tall thin form	Call for development	3.0
T982	Birch	C	Tall thin form	Call for development	3.0
T983	Birch	C	Tall thin form	Call for development	3.0
T984	Birch	C	Tall thin form	Call for development	3.0
T985	Birch	C	Tall thin form	Call for development	3.0
T986	Birch	C	Tall thin form	Call for development	3.0
T987	Birch	C	Tall thin form	Call for development	3.0
T988	Birch	C	Tall thin form	Call for development	3.0
T989	Birch	C	Tall thin form	Call for development	3.0
T990	Birch	C	Tall thin form	Call for development	3.0
T991	Birch	C	Tall thin form	Call for development	3.0
T992	Birch	C	Tall thin form	Call for development	3.0
T993	Birch	C	Tall thin form	Call for development	3.0
T994	Birch	C	Tall thin form	Call for development	3.0
T995	Birch	C	Tall thin form	Call for development	3.0
T996	Birch	C	Tall thin form	Call for development	3.0
T997	Birch	C	Tall thin form	Call for development	3.0
T998	Birch	C	Tall thin form	Call for development	3.0
T999	Birch	C	Tall thin form	Call for development	3.0

Tree No.	Species	Category	Notes	Tree Works	RPA
T1480	Acacia	C	Multiple stem defects	Call for development	4.2
T1481	Ash	C	2 stems, ash dieback	Call for development	4.7
T1482	Ash	C	Obvious ash dieback, tall thin form	Call for development	2.4
T1483	Sweet chestnut	B	Call for development	Call for development	3.6
T1484	Cherry	B	Call for development	Call for development	2.4
T1485	Sweet chestnut	B	Tall thin form	Call for development	1.2
T1486	Ash	C	Tall thin form, advanced ash dieback	Call for development	1.8
T1487	Birch	B	Call for development	Call for development	2.9
T1488	Weeping willow	C	Imbalanced, tall thin form	Call for development	5.3
T1489	Cherry	C	Severely imbalanced	Call for development	2.4
T1490	Weeping willow	C	Decay in trunk	Call for development	6.6
T1491	Oak	A	Imbalance because part of group	Call for development	10.8
T1492	Holly	B	Poorly formed, some stems with severe lean	Call for development	8.8
T1493	Oak	A	Stem damage and decayed stems, needs remedial work to retain	Call for development	2.4
T1494	Oak	A	Stems, needs remedial work to retain	Call for development	11.4
T1495	Holly	C	Severely imbalanced	Call for development	1.8
T1496	Beech	B	Call for development	Call for development	1.2
T1497	Beech	B	Call for development	Call for development	8.8
T1498	Holly	C	Decay in base, severely imbalanced	Call for development	2.4
T1499	Oak	B	Leaning trunk	Call for development	6.0
T1500	Holly	C	Partially supported by adjacent trees	Call for development	6.4
T1501	Oak	B	Part of group, imbalanced	Call for development	6.7
T1502	Oak	B	Call for development	Call for development	6.7
T1503	Oak	B	Call for development	Call for development	6.7
T1504	Holly	C	2 stems from ground level with weak unions	Call for development	1.7
T1505	Oak	C	Severe decay	Call for development	5.4
T1506	Oak	B	Defects in upper crown	Call for development	7.2
T1507	Oak	B	Decaying crown, needs work to be retained	Call for development	7.8
T1508	Beech	B	RPA modified by wall	Call for development	2.6
T1509	Oak	B	RPA modified by wall	Call for development	8.0
T1510	Yew	B	RPA modified by wall	Call for development	7.2
T1511	Beech	C	Severely imbalanced, RPA modified by wall	Call for development	3.6
T1512	Yew	B	RPA modified by wall	Call for development	10.0
T1513	Beech	C	Severely imbalanced, RPA modified by wall	Call for development	2.4
T1514	Yew	B	RPA modified by wall	Call for development	5.4
T1515	Beech	C	Severely imbalanced, RPA modified by wall	Call for development	5.2
T1516	Holly	C	Severely imbalanced, RPA modified by wall	Call for development	5.4
T1517	Yew	C	Severely imbalanced	Call for development	6.6
T1518	Beech	C	Severely imbalanced	Call for development	7.8
T1519	Beech	C	Large group of closely spaced tall thin stems, individually most trees very poorly formed, some dead and dying trees, many imbalanced trees, important as a landscape feature but individually the trees are low quality	Call for development	3.6
T1520	Ash, beech, sycamore	C	Call for development	Call for development	3.6
T1521	Sycamore	C	Severely imbalanced	Call for development	1.8
T1522	Beech	C	Interfering with adjacent tree	Call for development	3.0
T1523	Beech	C	Severely imbalanced, interfering with adjacent tree	Call for development	1.8
T1524	Yew	B	Partially supported	Call for development	8.6
T1525	Yew	B	Partially supported	Call for development	8.6
T1526	Yew	B	Partially supported	Call for development	8.6
T1527	Yew	B	Partially supported	Call for development	8.6
T1528	Yew	B	Partially supported	Call for development	8.6
T1529	Yew	B	Partially supported	Call for development	8.6
T1530	Yew	B	Partially supported	Call for development	8.6
T1531	Yew	B	Partially supported	Call for development	8.6
T1532	Yew	B	Partially supported	Call for development	8.6
T1533	Yew	B	Partially supported	Call for development	8.6
T1534	Yew	B	Partially supported	Call for development	8.6
T1535	Yew	B	Partially supported	Call for development	8.6
T1536	Yew	B	Partially supported	Call for development	8.6
T1537	Yew	B	Partially supported	Call for development	8.6
T1538	Yew	B	Partially supported	Call for development	8.6
T1539	Yew	B	Partially supported	Call for development	8.6
T1540	Yew	B	Partially supported	Call for development	8.6
T1541	Yew	B	Partially supported	Call for development	8.6
T1542	Yew	B	Partially supported	Call for development	8.6
T1543	Yew	B	Partially supported	Call for development	8.6
T1544	Yew	B	Partially supported	Call for development	8.6
T1545	Yew	B	Partially supported	Call for development	8.6
T1546	Yew	B	Multiple stems from ground level, tall thin form	Call for development	8.6
T1547	Yew	B	Call for development	Call for development	8.6
T1548	Sycamore	B	Call for development	Call for development	8.6
T1549	Sycamore	C	Stem defect of 3 m, supported by adjacent tree	Call for development	8.6
T1550	Yew	B	Partially supported	Call for development	8.6
T1551	Yew	C	Severely supported	Call for development	8.6
T1552	Yew	C	Partially supported	Call for development	8.6
T1553	Yew	C	Group of 7 individual trees, all imbalanced	Call for development	8.6
T1554	Sycamore	C	Tall thin form	Call for development	8.6
T1555	Yew	C	Call for development	Call for development	8.6
T1556	Unknown	C	Recording error	Call for development	8.6
T1557	Sycamore	C	Tall thin form, severe imbalance	Call for development	8.6
T1558	Yew	C	Severely imbalanced	Call for development	8.6
T1559	Yew	C	Multiple stems from ground level, some, severely imbalanced	Call for development	8.6
T1560	Yew	C	Call for development	Call for development	8.6
T1561	Yew	C	Severely imbalanced	Call for development	8.6
T1562	Yew	B	Call for development	Call for development	8.6
T1563	Holly	C	Decay in trunk	Call for development	8.6