

Tree Number and Species	Height (m)	DBH (mm)	Branch Spread (m)				Existing Height Above Ground Level of Canopy and 1 st Significant Branch (m)	Age Class	Estimated Remaining Contribution (Years) & Physiological Condition	Comments	BS Category & Tree Work Necessary for Development	RPA (m ²)	RPA (m)
			N	S	E	W							
T1 Oak <i>Quercus</i> sp.	16*	650*	5	5	5	5*	2.5 6 East	M	40+ Good	Subject of HBC TPO 1037. In adjacent garden no access, inspected visible parts over the fence. Truck appeared sound with no obvious defects. Poor past management. Major dead wood.	B2 Raise crown to crown break. Crown clean.	191	7.8
T2 Oak <i>Quercus</i> sp.	13*	500*	5	4	5	5*	4 3.5 West	M	40+ Good	Subject of HBC TPO 1037. In adjacent garden no access, inspected visible parts over the fence. Truck appeared sound with no obvious defects. Poor past management. Major dead wood. Hanging limb within east section of crown.	B2 Remove 3 small limbs east side at crown break. Crown reduce 1m east side	113	6
T3 Oak <i>Quercus</i> sp.	12*	500*	6	5	5	5*	3 5 Southwest	M	40+ Good	Subject of HBC TPO 1037. In adjacent garden no access, inspected visible parts over the fence. Truck appeared sound with no obvious defects. Poor past management. Major dead wood. Minor Squirrel damage.	B2 Crown clean	113	6

Tree Number and Species	Height (m)	DBH (mm)	Branch Spread (m)				Existing Height Above Ground Level of Canopy and 1 st Significant Branch (m)	Age Class	Estimated Remaining Contribution (Years) & Physiological Condition	Comments	BS Category & Tree Work Necessary for Development	RPA (m ²)	RPA (m)
			N	S	E	W							
T4 Oak <i>Quercus</i> sp.	14*	500*	4	3	4	6*	6 6 West	M	40+ Good	Subject of HBC TPO 1037. In adjacent garden no access, inspected visible parts over the fence. Truck appeared sound with no obvious defects. Poor past management. Major dead wood.	B2 Crown clean	113	6
T5 Oak <i>Quercus</i> sp.	10*	470	2	5	5	5	3 3 South	EM	40 Fair	Ivy extends from ground level up the stem to crown. Old pruning stubs. Water sprouts on stem.	B2 Remove	102	5.7
T6 Oak <i>Quercus</i> sp.	10*	260	2	2	2	2	6 6 West	SM	40 Fair	Ivy on stem. Small crown. Poor form.	C2 Remove	28	3

Tree Number and Species	Height (m)	DBH (mm)	Branch Spread (m)				Existing Height Above Ground Level of Canopy and 1 st Significant Branch (m)	Age Class	Estimated Remaining Contribution (Years) & Physiological Condition	Comments	BS Category & Tree Work Necessary for Development	RPA (m ²)	RPA (m)
			N	S	E	W							
T7 Oak <i>Quercus</i> sp.	18	470	3	5	4	4	5 5 Northeast	EM	40 Fair	Old bricks and tyres within the RPA, soil compacted. Crown break at 6m. Squirrel damage. Dead wood.	B2 Remove	102	5.7
T8 Oak <i>Quercus</i> sp.	18	470	4	5	5	2	3 5 South	EM	40 Fair	In contact with retaining. Compacted soil and steps within the RPA. Wound on stem at 1.5m east, minor decay evident. Squirrel damage and dead wood.	B2 Remove	102	5.7
T9 Oak <i>Quercus</i> sp.	18	600	7	5	6	7*	8 8 Northwest	M	40+ Good	Old bricks and tyres within the RPA, soil compacted. Dense Ivy extends from ground level onto scaffold limbs. Storm damage. Dead wood.	B2 Severe and remove Ivy. Crown clean.	163	7.2

Tree Number and Species	Height (m)	DBH (mm)	Branch Spread (m)				Existing Height Above Ground Level of Canopy and 1 st Significant Branch (m)	Age Class	Estimated Remaining Contribution (Years) & Physiological Condition	Comments	BS Category & Tree Work Necessary for Development	RPA (m ²)	RPA (m)
			N	S	E	W							
T10 Oak <i>Quercus</i> sp.	7	250	3	2	0	4	5 5 Northwest	SM	40 Fair	Poor form. Asymmetrical crown. Suppressed by T9 Oak.	C2 No work required	28	3
T11 Oak <i>Quercus</i> sp.	17	720	7*	7	7	7	2.5 6 Southwest	M	40+ Good	Minor Squirrel damage and dead wood. Storm damage.	B2 Crown clean. Remove 3 adventitious branches north and east	230	8.7
T12 Ash <i>Fraxinus excelsior</i>	16	400	2	5	4	4	8 8 South	EM	20 Fair	Dense Ivy extends from ground level onto all scaffold limbs limiting inspection. Poor past management. Evidence of minor die back, possibly Chalara Dieback caused by the fungus <i>Hymenoscyphus fraxineus</i>	C2 Remove	230	8.7

Tree Number and Species	Height (m)	DBH (mm)	Branch Spread (m)				Existing Height Above Ground Level of Canopy and 1 st Significant Branch (m)	Age Class	Estimated Remaining Contribution (Years) & Physiological Condition	Comments	BS Category & Tree Work Necessary for Development	RPA (m ²)	RPA (m)
			N	S	E	W							
T13 Oak <i>Quercus</i> sp.	17	1500 @ ground level	7*	9	5	6	3 4.5 Southwest	M	40 Fair	Compacted soil and play equipment within the RPA. Twin-stemmed from ground level. North stem bifurcates at 1m, poor branch union, long 'ears' on either side. South stem also bifurcates with long 'eared' branch union. South stem then bifurcates again. Branches removed historically at ground level on the west side and 1m on the south side. Minor dead wood and Squirrel damage.	C2 Remove	707	15
T14 Oak <i>Quercus</i> sp.	15	630	5	7	4	3	2 5 Southwest	M	40 Fair	On eastern boundary. Compacted soil. Ivy on lower stem only. Squirrel damage and minor dead wood.	B2 Crown clean. Remove 3 adventitious branches east and southwest	177	7.5
T15 Oak <i>Quercus</i> sp.	11*	700	4	4	6	4	1.5	M	40+ Good	Old building debris within the RPA. On raised bank. Ivy extends from ground level onto scaffold limbs, limited inspection. Past management. Water sprouts.	B2 Sever and remove Ivy. Crown clean. Raise crown to 4m.	238	8.7

Tree Number and Species	Height (m)	DBH (mm)	Branch Spread (m)				Existing Height Above Ground Level of Canopy and 1 st Significant Branch (m)	Age Class	Estimated Remaining Contribution (Years) & Physiological Condition	Comments	BS Category & Tree Work Necessary for Development	RPA (m ²)	RPA (m)
			N	S	E	W							
T16 Oak <i>Quercus</i> sp.	14*	470	4	5	0	4	1 1.5 South	EM	40 Good	Old building debris within the RPA. On raised bank. Ivy on lower stem only. Asymmetrical crown.	B2 Remove 2 lowest limbs. Reduce by 1m west.	102	5.7
T17 Ash <i>Fraxinus excelsior</i>	9	200	4	4	4	2	1 2.5 North	SM	20 Fair	Within shrub bed. Suppressed by adjacent trees. Dense Ivy extends onto scaffold limbs. Poor form.	C2 Remove	18	2.4
TG1 <i>Fraxinus excelsior</i>	14* Average	250 Average	8		4		1 4 East	EM	20-40 Good	Six self-seeded trees in adjacent garden. Poor form. One leaning over boundary into site. One in contact with fence. Evidence of minor die back, possibly Chalara Dieback caused by the fungus <i>Hymenoscyphus fraxineus</i>	C2 Remove tree leaning over fence and tree in contact with fence	28	3

Tree Number and Species	Height (m)	DBH (mm)	Branch Spread (m)				Existing Height Above Ground Level of Canopy and 1 st Significant Branch (m)	Age Class	Estimated Remaining Contribution (Years) & Physiological Condition	Comments	BS Category & Tree Work Necessary for Development	RPA (m ²)	RPA (m)
			N	S	E	W							
TG2 Oak <i>Quercus</i> sp.	14*	450 Average	8		8		2 4.5 East	EM	40 Good	Two Oaks. On raised bank. Ivy on stems. Minor past management. Birds nest in the south tree. Adventitious growth below crown break.	B2 Sever and remove Ivy. Crown clean. Raise crown to 4m	92	5.4
TG3 Ash, Field Maple, Oak <i>Fraxinus excelsior</i> , <i>Acer campestre</i> , <i>Quercus</i> sp.	15*	450 Average	22		8		1 2 West	SM EM	20-40 Fair Good	Six trees outside of the site, presumed to be under the Highway Agency or Havant Borough Councils management. Ivy on stems. Bird nests. Minor dead wood and Squirrel damage. No sign of recent management. Brick wall within the RPA.	B2 No work required	92	5.4