


## **Appendix A**

Existing Drainage  
Southern Water Records  
Architects Site Plan



- Existing Services Legend**
- Existing Surface Water Sewer (& Manhole)
  - Existing Foul Water Sewer (& Manhole)
  - Pipeline to be Removed / Abandoned
  - Existing CCTV Ducts
  - Existing HV Electric
  - Existing LV Electric
  - Existing Gas (From Records)
  - Existing BT Ducts
  - Existing Watermain



| COORDINATE SCHEDULE |            |           |       |                     |
|---------------------|------------|-----------|-------|---------------------|
| STATION             | EASTING    | NORTHING  | LEVEL | DESCRIPTION         |
| STN100              | 472211.633 | 99863.378 | 6.819 | HLTI NAIL IN TARMAC |
| STN101              | 472203.649 | 99771.003 | 7.076 | HLTI NAIL IN TARMAC |
| STN102              | 472202.090 | 99754.636 | 7.041 | HLTI NAIL IN TARMAC |
| STN103              | 472199.362 | 99723.104 | 6.912 | HLTI NAIL IN TARMAC |
| STN104              | 472189.807 | 99746.593 | 6.771 | HLTI NAIL IN TARMAC |
| STN105              | 472144.044 | 99763.579 | 6.845 | HLTI NAIL IN TARMAC |
| STN106              | 472128.220 | 99776.117 | 6.735 | HLTI NAIL IN TARMAC |

P1 26.04.16 Drawn MJR  
Rev. Date Description Issued By

Information

**calcinotto**  
CONSULTING STRUCTURAL CIVIL AND ENVIRONMENTAL ENGINEERS  
ADDRESS : 2nd Floor, Jonsen House, 43 Commercial Road, Poole, Dorset BH14 0HU  
T: 0044 1202 237237 W: www.calcinotto.co.uk E: admin@calcinotto.co.uk

Client. **McCarthy & Stone**  
Project Title. **Hayling Island**  
Drawing Title. **Existing Drainage**

SEWER RECORDS PAGE 1 OF 2

99899



99611

|                                      |
|--------------------------------------|
| O.S. REF.                            |
| <b>SZ7299NW</b>                      |
| Title: 204610_Hayling Billy Pub, 117 |

|           |            |
|-----------|------------|
| Drawn by: | kumaria    |
| Scale:    | 1:1250     |
| Date:     | 26/10/2015 |

The positions of pipes shown on this plan are believed to be correct, but Southern Water Services Ltd accept no responsibility in the event of inaccuracy.  
The actual positions should be determined on site.  
**WARNING: BAC pipes are constructed of Bonded Asbestos Cement**  
**WARNING: Unknown (UNK) materials may include Bonded Asbestos Cement**  
Based upon Ordnance Survey Digital Data with the permission of the controller of H.M.S.O. Crown Copyright Reserved  
Licence No. WU 298530.



N



472401



|           |        |                  |    |    |
|-----------|--------|------------------|----|----|
| A         | 040216 | LANDSCAPE UPDATE | CK | CK |
| REVISIONS |        |                  |    |    |

NOTES:

FOR GREENFILE

0 2 4 6 8 10 12 14 16 18 20m

N

McCarthy & Stone

Scale @ A1: 1/200

Date: JANUARY 2016

Drawn by: CK

Checked by: GG

CLIENT

TITLE

ELM GROVE, HAYLING ISLAND

PROPOSED SITE PLAN

Drawing No: SO\_2267\_02\_AC\_010

Revision: A

HGP ARCHITECTS

FURZEHALL FARM, WICKHAM ROAD  
FARDEHAM, HAMPSHIRE, PO16 7JH

T: 01329 283 225  
F: 01329 237 004  
E: EMAIL@HGP-ARCHITECTS.CO.UK  
W: WWW.HGP-ARCHITECTS.CO.UK

HGP Architects Ltd.  
Copyright Reserved.  
Check dims. on site.