

The proposed parking located under T1 Oak would have an unsatisfactorily close relationship with the tree in terms of finding a level in relation to under ground constraints and also above ground constraints would be a problem parking a car right under the canopy of the tree at this distance.

The parking proposed under T3 Beech is again an unsatisfactory relationship.

Other options within the site should be explored where the trees will not be compromised.