

Inspections

1. A site sketch plan showing the tree and garden wall is appended separately as an A4 pdf, and 3 sketch views A B & C are also appended.
2. Some typical photographs of the inspections follow:-



Typical view on rear viewing from house showing mature Sweet Chestnut with garden wall behind



Left hand corner behind tree – wall has been pushed over 70mm at top



View from neighbours side – Wall leans 70mm at top – wall is unsafe





View from our side showing wide trunk at base and full height vertical crack to right of tree (see sketch view A appended separately)



Damage to base of wall (neighbours side)





General view on neighbours side – shows tree is in close proximity to neighbours house & rear conservatory (tree is 3.5m from corner of conservatory)



View along wall on neighbours side – shows wall leaning 70mm at top

