

Address: Harbour View, Marine Walk, Hayling Island, Hampshire



Front elevation



Rear elevation



Chimney and delaminating tiles



Bonnet hip tiles standing proud



Distorted gutter to rear conservatory



Drainage gully



Saplings adjoining exterior wall



Garage



Garage door frame




Middle drainage chamber



Rear drainage chamber




Well




Roof void and redundant tank



Underlay



Water tanks



Electrical installation



Boiler in chimney recess



Staining to chimney breast



Lead wastes to bath



Water cylinder