

LEVEL MONITORING

for Subsidence Management Services

10 Linda Grove, Waterlooville, Hampshire, PO8 8UX

Client:	Subsidence Management Services
Client Contact:	Jose Lopez
Claim Number:	13EQ602273
Client Reference:	IFS-AVI-ROF-13-0044763
Policy Holder:	Mrs Lynda Emmott
Report Date:	27 March 2015
Our Ref:	M1320



Level Monitoring Readings

The following table shows the reading levels of the various Level Monitoring Station points.

Date	1	2	3	4	5	6
30/11/2013	10.3214	10.3764	10.3752	10.3460	10.3347	10.3603
27/01/2014	10.3220	10.3762	10.3754	10.3475	10.3376	10.3605
19/03/2014	10.3222	10.3771	10.3754	10.3480	10.3388	10.3595
10/05/2014	10.3209	10.3759	10.3748	10.3477	10.3394	10.3593
16/07/2014	10.3207	10.3754	10.3742	10.3438	10.3340	10.3588
08/10/2014	10.3203	10.3755	10.3740	10.3380	10.3272	10.3568
03/02/2015	10.3211	10.3765	10.3747	10.3416	10.3328	10.3575
24/03/2015	10.3206	10.3756	10.3747	10.3416	10.3332	10.3573



Level Monitoring Difference Graphs

The following graphs display the progressive movement that each Level Monitoring Station recorded at each separate site visit date to give an overall look at how much the property is moving.



Level Monitoring Displacement Map

The following image shows an isometric representation of the movement of the property, based on the Level Monitoring Stations that were installed.



Site Visit Notes

Level Readings are made relative to a Drain surround located within the road to the front of the property. It has an assumed value of 10.0000m. Please advise if this is not acceptable.

Site Visit: 30 November 2013

Level Readings have been made relative to a man hole cover surround located within the road to the front of the property. It has an assumed value of 10.0000m. please advise if you require an alternative location or a Deep Datum installing?