

he 'Infiltration SUDS' report is based on a generic desk study and does not reflect actual ground conditions as far as I am able to tell. The report itself highlights areas of the site where SUDS are not appropriate but the drainage design then puts a soakaway in that area.

I would suggest we need to see an actual ground investigation at the site to determine the actual conditions, rather than generic results from the desk study.

There has been a history of water running off these fields into the road and we need to ensure this is not exacerbated.

Best wishes

Steve Mountain
Project Engineer
Transport & Implementation Team
Environment & Neighbourhood Quality
Havant Borough Council
Southmoor Offices and Depot, 2 Penner Road, Havant, PO9 1QH
[\[Location Map\]](#) [\[Get here by bike \(journey planner\)\]](#) [\[Get here by public transport \(journey planner\)\]](#) [\[Why not Car Share?\]](#)

Telephone: 023 9244 6444
Fax: 023 9249 8031
HBC on the web: www.havant.gov.uk