

Both trees are showing signs of decline suffering phytophthora and as such their SULE is greatly reduced.

As such these trees should not be considered a constraint to development (excluding one tree outside the curtilage).

The AMS & TIP is considered adequate in the circumstances and as such there is no objection to the project.

Two horse chestnuts - standards must be planted to ensure sustainability

on site. and the area.

The AMS and TPP
must be constructed
and the trees should
be monitored for
any signs of stress
and/or decline.

Should these trees fail
there are concerns
over H. & S. and the
highway.

A handwritten signature in dark ink, consisting of stylized, overlapping loops and a horizontal line at the bottom.