

Pictures of 4 Silvertrees current tarmac driveway. Car number 3 has to park on lawn to allow 2 other cars to reverse off drive



Proposed location of new car port.

Existing conifer hedge and shed to be removed to allow car port to be set as far as possible into corner

