

Site Investigation Photograph 57	
Date: 22/07/21	
Direction Photograph Taken: n/a.	
Description: TP6.01	

Site Investigation Photograph 58	
Date: 22/07/21	
Direction Photograph Taken: n/a.	
Description: TP6.01 side walls.	

Site Investigation Photograph 59	
Date: 22/07/21	
Direction Photograph Taken: n/a.	
Description: TP6.01 arisings.	

Site Investigation Photograph 60	
Date: 22/07/21	
Direction Photograph Taken: n/a.	
Description: TP6.01 backfilled with arisings after completion of works	

Site Investigation Photograph 61	
Date: 22/07/21	
Direction Photograph Taken: n/a.	
Description: TP6.02.	

Site Investigation Photograph 62	
Date: 22/07/21	
Direction Photograph Taken: n/a.	
Description: TP6.02 side walls.	

Site Investigation Photograph 63	
Date: 22/07/21	
Direction Photograph Taken: n/a.	
Description: TP6.02 orange brown and light grey mottled sandy clay.	

Site Investigation Photograph 64	
Date: 22/07/21	
Direction Photograph Taken: n/a.	
Description: TP6.02 arisings.	

Site Investigation Photograph 65	
Date: 22/07/21	
Direction Photograph Taken: n/a.	
Description: TP6.03	

Site Investigation Photograph 66	
Date: 22/07/21	
Direction Photograph Taken: n/a.	
Description: TP6.03 arisings.	

Site Investigation Photograph 67	
Date: 23/07/21	
Direction Photograph Taken: n/a.	
Description: TP6.05.	

Site Investigation Photograph 68	
Date: 23/07/21	
Direction Photograph Taken: n/a.	
Description: TP6.05 orange brown and light grey mottled clay.	

Site Investigation Photograph 69		Date: 23/07/21
Direction Photograph Taken: n/a.		Description: TP6.05 arisings.

Site Investigation Photograph 70		Date: 23/07/21
Direction Photograph Taken: n/a.		Description: TP6.09.

Site Investigation Photograph 71	
Date: 23/07/21	
Direction Photograph Taken: n/a.	
Description: TP6.09 side walls.	

Site Investigation Photograph 72	
Date: 23/07/21	
Direction Photograph Taken: n/a.	
Description: TP6.09 clay pipe.	

Site Investigation Photograph 73		
Date: 23/07/21		
Direction Photograph Taken: n/a.		
Description: TP6.09 arisings.		

Site Investigation Photograph 74		
Date: 23/07/21		
Direction Photograph Taken: n/a.		
Description: TP6.08.		

Site Investigation Photograph 75	
Date: 23/07/21	
Direction Photograph Taken: n/a.	
Description: TP6.08 side walls.	

Site Investigation Photograph 76	
Date: 23/07/21	
Direction Photograph Taken: n/a.	
Description: TP6.08 arisings.	

Site Investigation Photograph 77	
Date: 23/07/21	
Direction Photograph Taken: n/a.	
Description: TP6.07.	

Site Investigation Photograph 78	
Date: 23/07/21	
Direction Photograph Taken: n/a.	
Description: TP6.07 side walls.	

Site Investigation Photograph 79	
Date: 23/07/21	
Direction Photograph Taken: n/a.	
Description: TP6.07 arisings.	

Site Investigation Photograph 80	
Date: 23/07/21	
Direction Photograph Taken: n/a.	
Description: TP6.06.	

Site Investigation Photograph 81	
Date: 23/07/21	
Direction Photograph Taken: n/a.	
Description: TP6.06 arisings.	

Site Investigation Photograph 82	
Date: 23/07/21	
Direction Photograph Taken: n/a.	
Description: TP6.04.	

Site Investigation Photograph 83	
Date: 23/07/21	
Direction Photograph Taken: n/a.	
Description: TP6.04 arisings.	

Site Investigation Photograph 84	
Date: 27/07/21	
Direction Photograph Taken: n/a.	
Description: WS4.02.	

Site Investigation Photograph 85	
Date: 28/07/21	
Direction Photograph Taken: n/a.	
Description: Setting up WS rig at location WS4.05.	

Site Investigation Photograph 86	
Date: 28/07/21	
Direction Photograph Taken: n/a.	
Description: WS4.05.	

Site Investigation Photograph 87	
Date: 28/07/21	
Direction Photograph Taken: n/a.	
Description: Monitoring well installed at WS4.05.	

Site Investigation Photograph 88	
Date: 28/07/21	
Direction Photograph Taken: n/a.	
Description: WS4.06	

Site Investigation Photograph 89	
Date: 28/07/21	
Direction Photograph Taken: n/a.	
Description: TP4.07 excavated by hand to 0.80m bgl.	

Site Investigation Photograph 90	
Date: 28/07/21	
Direction Photograph Taken: n/a.	
Description: WS7.03.	

Site Investigation Photograph 91	
Date: 28/07/21	
Direction Photograph Taken: n/a.	
Description: Monitoring well installed at WS7.03.	

Site Investigation Photograph 92	
Date: 28/07/21	
Direction Photograph Taken: n/a.	
Description: WS7.02.	

Site Investigation Photograph 93	
Date: 28/07/21	
Direction Photograph Taken: n/a.	
Description: WS7.05.	

Site Investigation Photograph 94	
Date: 29/07/21	
Direction Photograph Taken: n/a.	
Description: WS6.05	

Site Investigation Photograph 95	
Date: 29/07/21	
Direction Photograph Taken: n/a.	
Description: WS6.04.	

Site Investigation Photograph 96	
Date: 29/07/21	
Direction Photograph Taken: n/a.	
Description: Monitoring well installed at WS6.04.	

Site Investigation Photograph 97	
Date: 29/07/21	
Direction Photograph Taken: n/a.	
Description: WS6.01.	

Site Investigation Photograph 98	
Date: 26/07/21	
Direction Photograph Taken: n/a.	
Description: WS1.01.	

Site Investigation Photograph 99	
Date: 26/07/21	
Direction Photograph Taken: n/a.	
Description: WS1.02 hand pit arisings.	

Site Investigation Photograph 100	
Date: 26/07/21	
Direction Photograph Taken: n/a.	
Description: WS1.02.	

Site Investigation Photograph 101	
Date: 27/07/21	
Direction Photograph Taken: n/a.	
Description: WS4.03.	

Site Investigation Photograph 102	
Date: 27/07/21	
Direction Photograph Taken: n/a.	
Description: WS4.04.	

Site Investigation Photograph 103	
Date: 27/07/21	
Direction Photograph Taken: n/a.	
Description: Monitoring well installed at WS4.04.	

Site Investigation Photograph 104	
Date: 28/07/21	
Direction Photograph Taken: n/a.	
Description: WS7.04.	

Site Investigation Photograph 105	
Date: 28/07/21	
Direction Photograph Taken: n/a.	
Description: WS7.06.	

Site Investigation Photograph 106	
Date: 28/07/21	
Direction Photograph Taken: n/a.	
Description: WS7.01.	

Site Investigation Photograph 107	
Date: 28/07/21	
Direction Photograph Taken: n/a.	
Description: WS6.07.	

Site Investigation Photograph 108	
Date: 27/07/21	
Direction Photograph Taken: n/a.	
Description: WS6.06.	

Site Investigation Photograph 109	
Date: 29/07/21	
Direction Photograph Taken: n/a.	
Description: WS6.03.	

Site Investigation Photograph 110	
Date: 10/08/21	
Direction Photograph Taken: n/a.	
Description: Wooden post installed next to monitoring wells.	

Site Investigation Photograph 111	
Date: 10/08/21	
Direction Photograph Taken: n/a.	
Description: Wooden post installed next to monitoring wells.	

Site Investigation Photograph 112	
Date: 26/08/21	
Direction Photograph Taken: n/a.	
Description: HP7.01 excavated to 1.00m bgl.	