

With every community, we redefine what's possible.

Stantec is a global leader in sustainable engineering, architecture, and environmental consulting. The diverse perspectives of our partners and interested parties drive us to think beyond what's previously been done on critical issues like climate change, digital transformation, and future-proofing our cities and infrastructure. We innovate at the intersection of community, creativity, and client relationships to advance communities everywhere, so that together we can redefine what's possible.

Stantec UK Limited

Great Suffolk Yard
127-131 Great Suffolk Street
London
SE1 1PP
UNITED KINGDOM
stantec.com



Appendix C Exploratory Hole Location Plan, Exploratory Hole Logs and Photographs



Site Investigation Photograph 1	
Date: 21/07/21	
Direction Photograph Taken: n/a.	
Description: TP7.07	

Site Investigation Photograph 2	
Date: 21/07/21	
Direction Photograph Taken: n/a.	
Description: TP7.07 – man- made materials.	

Site Investigation Photograph 3	
Date: 21/07/21	
Direction Photograph Taken: n/a.	
Description: TP7.07 – arisings.	

Site Investigation Photograph 4	
Date: 21/07/21	
Direction Photograph Taken: n/a.	
Description: TP7.07 backfilled with arisings after completion of works.	

Site Investigation Photograph 5	
Date: 21/07/21	
Direction Photograph Taken: n/a.	
Description: TP7.09.	

Site Investigation Photograph 6	
Date: 21/07/21	
Direction Photograph Taken: n/a.	
Description: TP7.09 – brick fragments (possible clay pipe).	

Site Investigation Photograph 7	
Date: 21/07/21	
Direction Photograph Taken: n/a.	
Description: TP7.09 arisings.	

Site Investigation Photograph 8	
Date: 21/07/21	
Direction Photograph Taken: n/a.	
Description: TP7.09 backfilled with arisings after completion of works.	

Site Investigation Photograph 9	
Date: 21/07/21	
Direction Photograph Taken: n/a.	
Description: TP7.08.	

Site Investigation Photograph 10	
Date: 21/07/21	
Direction Photograph Taken: n/a.	
Description: TP7.08 arising.	

Site Investigation Photograph 11	
Date: 21/07/21	
Direction Photograph Taken: n/a.	
Description: TP7.11.	

Site Investigation Photograph 12	
Date: 21/07/21	
Direction Photograph Taken: n/a.	
Description: TP7.11 arisings.	

Site Investigation Photograph 13	
Date: 21/07/21	
Direction Photograph Taken: n/a.	
Description: TP7.11 backfilled with arisings after completion of works.	

Site Investigation Photograph 14	
Date: 22/07/21	
Direction Photograph Taken: n/a.	
Description: TP7.10.	

Site Investigation Photograph 15	
Date: 22/07/21	
Direction Photograph Taken: n/a.	
Description: TP7.10 arisings.	

Site Investigation Photograph 16	
Date: 22/07/21	
Direction Photograph Taken: n/a.	
Description: TP7.10 backfilled with arisings after completion of works.	

Site Investigation Photograph 17	
Date: 22/07/21	
Direction Photograph Taken: n/a.	
Description: TP7.06.	

Site Investigation Photograph 18	
Date: 22/07/21	
Direction Photograph Taken: n/a.	
Description: TP7.06 side walls.	

Site Investigation Photograph 19	
Date: 22/07/21	
Direction Photograph Taken: n/a.	
Description: TP7.06 arisings.	

Site Investigation Photograph 20	
Date: 22/07/21	
Direction Photograph Taken: n/a.	
Description: TP7.05.	

Site Investigation Photograph 21	
Date: 22/07/21	
Direction Photograph Taken: n/a.	
Description: TP7.05 side walls.	

Site Investigation Photograph 22	
Date: 22/07/21	
Direction Photograph Taken: n/a.	
Description: TP7.05 arising.	

Site Investigation Photograph 23	
Date: 22/07/21	
Direction Photograph Taken: n/a.	
Description: TP7.03.	

Site Investigation Photograph 24	
Date: 22/07/21	
Direction Photograph Taken: n/a.	
Description: TP7.03 arisings.	

Site Investigation Photograph 25	
Date: 21/07/21	
Direction Photograph Taken: n/a.	
Description: TP7.02.	

Site Investigation Photograph 26	
Date: 21/07/21	
Direction Photograph Taken: n/a.	
Description: TP7.02 arisings.	

Site Investigation Photograph 27		
Date: 21/07/21		
Direction Photograph Taken: n/a.		
Description: TP7.02 backfilled with arising after completion of works.		

Site Investigation Photograph 28		
Date: 21/07/21		
Direction Photograph Taken: n/a.		
Description: TP7.04.		

Site Investigation Photograph 29	
Date: 21/07/21	
Direction Photograph Taken: n/a.	
Description: TP7.04 side walls.	

Site Investigation Photograph 30	
Date: 21/07/21	
Direction Photograph Taken: n/a.	
Description: TP7.01.	

Site Investigation Photograph 31	
Date: 21/07/21	
Direction Photograph Taken: n/a.	
Description: TP7.01 arisings.	

Site Investigation Photograph 32	
Date: 21/07/21	
Direction Photograph Taken: n/a.	
Description: TP4.01.	

Site Investigation Photograph 33	
Date: 21/07/21	
Direction Photograph Taken: n/a.	
Description: TP4.01 arisings.	

Site Investigation Photograph 34	
Date: 21/07/21	
Direction Photograph Taken: n/a.	
Description: TP4.01 being backfilled with gravel and pipework for infiltration testing.	

Site Investigation Photograph 35		
Date: 22/07/21		
Direction Photograph Taken: n/a.		
Description: TP4.02.		

Site Investigation Photograph 36		
Date: 22/07/21		
Direction Photograph Taken: n/a.		
Description: TP4.02 arisings.		

Site Investigation Photograph 37	
Date: 22/07/21	
Direction Photograph Taken: n/a.	
Description: TP4.03.	

Site Investigation Photograph 38	
Date: 22/07/21	
Direction Photograph Taken: n/a.	
Description: TP4.03 side walls.	

Site Investigation Photograph 39	
Date: 22/07/21	
Direction Photograph Taken: n/a.	
Description: TP4.03 arisings.	

Site Investigation Photograph 40	
Date: 22/07/21	
Direction Photograph Taken: n/a.	
Description: TP4.04.	

Site Investigation Photograph 41	
Date: 22/07/21	
Direction Photograph Taken: n/a.	
Description: TP4.03 side walls.	

Site Investigation Photograph 42	
Date: 22/07/21	
Direction Photograph Taken: n/a.	
Description: TP4.04 arisings.	

Site Investigation Photograph 43	
Date: 23/07/21	
Direction Photograph Taken: n/a.	
Description: TP4.05 backfilled with arisings after completion of works.	

Site Investigation Photograph 44	
Date: 23/07/21	
Direction Photograph Taken: n/a.	
Description: TP4.06.	

Site Investigation Photograph 45	
Date: 23/07/21	
Direction Photograph Taken: n/a.	
Description: TP4.06 side walls.	

Site Investigation Photograph 46	
Date: 23/07/21	
Direction Photograph Taken: n/a.	
Description: TP4.06 arisings.	

Site Investigation Photograph 47	
Date: 23/07/21	
Direction Photograph Taken: n/a.	
Description: TP1.01.	

Site Investigation Photograph 48	
Date: 23/07/21	
Direction Photograph Taken: n/a.	
Description: TP1.01 arisings.	

Site Investigation Photograph 49		
Date: 23/07/21		
Direction Photograph Taken: n/a.		
Description: TP1.01 backfilled with arising after completion of works.		

Site Investigation Photograph 50		
Date: 23/07/21		
Direction Photograph Taken: n/a.		
Description: TP1.02.		

Site Investigation Photograph 51	
Date: 23/07/21	
Direction Photograph Taken: n/a.	
Description: TP1.02 arisings.	

Site Investigation Photograph 52	
Date: 23/07/21	
Direction Photograph Taken: n/a.	
Description: TP1.04.	

Site Investigation Photograph 53	
Date: 23/07/21	
Direction Photograph Taken: n/a.	
Description: TP1.04 arisings.	

Site Investigation Photograph 54	
Date: 23/07/21	
Direction Photograph Taken: n/a.	
Description: TP1.03.	

Site Investigation Photograph 55		
Date: 23/07/21		
Direction Photograph Taken: n/a.		
Description: TP1.03 arisings.		

Site Investigation Photograph 56		
Date: 23/07/21		
Direction Photograph Taken: n/a.		
Description: TP1.03 backfilled with arisings after completion of works.		