DAMAGE BY IVY
FROM NO 26 SIDE TO
ORIGINAL PANELS FITTED
IN YEAR 2000
REPLACED. 23-6-2017