

9 View looking east with affected yew and headstones in centre of picture.



10 The west end of the church with its ceremonial entrance and recently laid reconstructed stone paving. It is proposed to continue the paving to the north extension.