

5 The valley gutter with the church also collects rainwater from the chancel and choir vestry.



6 The assembly of rainwater goods and poor junction detail has resulted in major water ingress



7 North wall of adjoining choir vestry with bolder flint and dressed stone quoins and plinth cap.



8 North aisle north wall with coursed bolder flint with stone quoins to buttresses and plinth cap.