AS THE TREE BELOW ARE OVERHANGING THE PAVEMENT, THEY NEED TO BE TRIMMED BACK