

TREE WORK APPLICATION – Forty Acre Farm Harbour Place, Bedhampton

9th February 2021

SUMMARY

I write to confirm my visit to the above site to inspect several trees on the south western boundary, where new foul drainage route is proposed. I am instructed to inspect and provide recommendations and advice on the issues that need to be addressed in terms of works required to allow the services to be installed. I stress that this is a brief summary for the purposes of specifying appropriate work based on the information available.



I visited the site on the 2nd February 2021. All my observations were from ground level without detailed investigation. The weather at the time of inspection was dull and damp, with average visibility.

PROPOSED WORKS

The proposed work is to fell two trees in G62 either side of the dead trees numbered G63. Please refer to the attached plan extracts for more details.

The new foul drain requires a minimum easement of 6m. The two dead trees G63 stand approximately 2m apart, with the two trees either side a further 2m beyond them, so to achieve

TREE WORK APPLICATION – Forty Acre Farm Harbour Place, Bedhampton

the necessary easement with suitable working space and protect the remaining trees we consider that the removal of two live trees will be sensible.

We respectfully request that you grant consent for the felling of two trees in G62 either side of the dead trees in G63.

Please contact me if you require any further clarification on any of these points.

Chris Alder **MSc HNDArb FArborA MICFor RCarborA**



Image 1: G63 two dead trees, with the two live trees in G62 to be removed either side.



Image 2: G62 viewed looking north