

Good Morning Denise,
Further to our recent telephone conversation I attach a photograph of the relevant trees in the plots behind my client's property. This was taken late last week. It will be seen that the trees are in good condition and I would also qualify the following.

1. The trees within Nos. 17 and 20 Wedgewood Way were in position when these houses were constructed approximately 8 years ago. They have not shown any signs of distress caused by the development.
2. These trees have also been subject of Planning Applications over the last 4 years. [Ref: APP/16/00793. APP/20/00158. APP/20/00574.] Approval was granted for reshaping, limb removal and crown reductions. Again they have not shown any signs of distress.

When taking the above into account and the fact that the gazebo has no foundations and is sitting on a paved area that has been in place for over 15 years it is felt that the welfare of these rightly protected trees cannot be compromised.

Should you require any further information please advise me accordingly.

Kind Regards,

Don Boddy.

The Project Support Practice.

