
Unable to survey beyond boundary fence due to locked gate & no alternative safe access.
Dense Vegetation
Unable to survey boundary
Unable to thread & Sond. Unable to produce a signal through CI pipe. Unable to trace.
Chamber Extents
MH CL 6.32
MH CL 6.16 Flooded UTS Blocked at 4.15m
Flow Control Chamber Extents
MH CL 6.24 IL 5.24
Cut Vegetation
Shed
Greenhouse
Limited survey due to excess debris within this whole area. No other MH's visible.
Gravel
Cutting in progress Unable to survey
Wall
Unable to thread further
Dumped Materials
Concrete Base
Tarmac
SV under car Unable to survey.
Lighting
Unable to survey (storage)
Concrete
Grass Field
West Street
Soundex Connection
MH 06 CL 6.35
MH CL 6.27
MH CL 6.46 IL 6.41 (Inlet)
MH CL 7.12 IL 5.72
MH CL 6.99 IL 5.89
T1 E 470929.170 N 106528.377 Z 6.360
T2 E 470925.103 N 106528.433 Z 6.974
T3 E 470933.977 N 106518.537 Z 6.870
T4 E 470944.447 N 106543.987 Z 6.615
T5 E 470944.146 N 106528.813 Z 6.669
T6 E 470944.651 N 106528.045 Z 6.672
T7 E 470944.651 N 106528.045 Z 6.672
T8 E 470944.651 N 106528.045 Z 6.672
Ø150 Approx
Ø400 Approx
Ø225 Approx
Ø300 Approx
Ø375 Approx
Ø450 Approx
Ø600 Approx
Ø750 Approx
Ø900 Approx
Ø1050 Approx
Ø1200 Approx
Ø1350 Approx
Ø1500 Approx
Ø1650 Approx
Ø1800 Approx
Ø1950 Approx
Ø2100 Approx
Ø2250 Approx
Ø2400 Approx
Ø2550 Approx
Ø2700 Approx
Ø2850 Approx
Ø3000 Approx
Ø3150 Approx
Ø3300 Approx