

Hello David

Thank you for your letter of 13th January explaining the measures required for you to make a positive recommendation. Our response is as follows:

1 Landscaping. As recommended we propose, a double staggered line of mixed native trees to include some evergreens, to the north and east sides of the clamp, as plan attached.

2 Painting. As recommended we propose painting the metalwork in greengage (Trade Paint, paints4trade.com) which is a similar colour to the adjoining barn.

3 Materials. We do not agree with a timber boarding, it seems unnecessary as it will be hidden behind the planting. There is mature planting on the north boundary closest to our neighbours property and this will be allowed to grow taller to mask the concrete panels.

4 Drainage and potential water pollution. The site is well drained and we have marked the soakaway on the plan. There was existing drainage around the previous silage clamp and we make sure this is fully functioning. Please note there is a fall from North to South so there should be no danger to our neighbours pond and well.

For your information, the sewer mentioned in your correspondence, runs from south to north some 30 metres to the west of the clamp.

We hope this is sufficient information but please come back to us if you require anything further.

Kind regards

Mary Pike
A H Brown Ltd