

As stated on drawing 17070_112, the garage was re-built using the existing foundations and ground slab. Subsequently, there was no adverse effect on the adjacent trees.