

Planning Consultation – HVE013 – Bosmere Junior School, South Street, HAVANT PO9 1DA

Date: 22 February 2018

Additional Comments: on Arboriculture Report ;

BS 5837 Report on the Trees in Relation to Bosmere Junior School in Havant rev 1 dated 05/12/17

Comments:

01. Tree No 17 is Not to be removed. Report revised with new plans Figure 2 page 11 and Drawing 3 page 30
 02. Arboriculture supervision is recommended for helical screw operations, as this will be the most impact to the remaining trees.
 03. The clearing of a 2m strip of ground vegetation and some epimoric growth to allow clearance for works, will not impact any remaining trees.
 04. Regarding new planting for poor form self set trees under the canopy of the larger trees, these specimens were recommended to be removed as good arboricultural practice to increase light and biodiversity in this densely wooded area. It is not necessary to plant new specimens, as the site has plenty of tree cover already with its own small woodland, and there is very limited space left within the grounds to support new trees.
 05. These works are important safety requirements to stabilise this wall, and I believe this method was the most logical and best way to prevent any major impact to the trees.
-

Laurence Johns BSc

Arboriculture and Grounds Management.

HCC Property Services

Room 3.01, Third Floor

Castle Avenue

Winchester, Hampshire, SO23 8DS

M: 07880384056

E: Laurence.Johns@hants.gov.uk

www.hants.gov.uk/propertyservices