




Due to distance from boundary, lower height of new units, new landscaping and boundary fence, overlooking of neighbouring amenity areas is kept to minimum.


Guide to Views



Due to distance from boundary, lower height of new units, new landscaping and boundary fence, overlooking of neighbouring amenity areas is kept to minimum.

Aerial view

Schematic view looking towards the new Units



Due to distance from boundary, lower height of new units, new landscaping and boundary fence, overlooking of neighbouring amenity areas is kept to minimum.

Street view
Schematic view with no 15 Billett Avenue on left
and the lower height units on the right.

image by Martin Ralph Architects
v3. January 2018



Due to distance from boundary, lower height of new units, new landscaping and boundary fence, overlooking of neighbouring amenity areas is kept to minimum.

Aerial view

Schematic view looking towards the new Units




Due to distance from boundary, lower height of new units, new landscaping and boundary fence, overlooking of neighbouring amenity areas is kept to minimum.

View 4

Schematic view looking from the rear garden of
no 15 Billett Avenue towards new Unit 4

image by Martin Ralph Architects
v3. January 2018



Due to distance from boundary, lower height of new units, new landscaping and boundary fence, overlooking of neighbouring amenity areas is kept to minimum.

View 3

Schematic view looking from the rear garden of
no 15 Billett Avenue towards new Unit 3

image by Martin Ralph Architects
v3. January 2018




Due to distance from boundary, lower height of new units, new landscaping and boundary fence, overlooking of neighbouring amenity areas is kept to minimum.

View 2

Schematic view looking from the rear garden of no 15 Billett Avenue towards new Unit 2

image by Martin Ralph Architects
v3. January 2018




Due to distance from boundary, lower height of new units, new landscaping and boundary fence, overlooking of neighbouring amenity areas is kept to minimum.

View 1

Schematic view looking from the front garden of no 15 Billett Avenue towards new Unit 1

image by Martin Ralph Architects
v3. January 2018




Due to distance from boundary,
lower height of new units, new
landscaping and boundary fence,
overlooking of neighbouring
amenity areas is kept to minimum.

View 5

Schematic view looking from the pool area of no 15 Billett Avenue towards new Units

image by Martin Ralph Architects
v3. January 2018




Due to distance from boundary, lower height of new units, new landscaping and boundary fence, overlooking of neighbouring amenity areas is kept to minimum.

View 6

Schematic view looking out of bedroom window of Unit 4 towards boundary to no 15.

image by Martin Ralph Architects
v3. January 2018




Due to distance from boundary, lower height of new units, new landscaping and boundary fence, overlooking of neighbouring amenity areas is kept to minimum.

View 7

Schematic view looking out of bedroom window
of Unit 3 towards boundary to no 15.

image by Martin Ralph Architects
v3. January 2018



Due to distance from boundary,
lower height of new units, new
landscaping and boundary fence,
overlooking of neighbouring
amenity areas is kept to minimum.

View 8

Schematic view looking out of bedroom window
of Unit 2 towards boundary to no 15.

image by Martin Ralph Architects
v3. January 2018