

Mrs. B. Crawford
Planning Services
Havant Borough Council
Public Service Plaza
Civic Centre Road
Havant
Hampshire
PO9 2AX

Date: 20th September 2017
Enquiries to: Stuart York
Direct Line: 023 8047 8566
Our reference: app/17
Your reference: APP/17/00875

Dear Mrs. Crawford,

68 BOTLEY DRIVE, HAVANT, PO9 4QY

Thank you for your letter of the 8th September 2017 and the opportunity to comment upon the application. Having considered the application I have the following comments to make with reference to crime prevention.

Botley Drive is place from which we regularly receive reports of crime. Crimes reported include: assault, robbery and criminal damage. It is against this background that my comments are made.

Automatic Teller Machines (ATMs) offer a range of opportunities for crime. Those using and replenishing the machine are vulnerable and the machine itself can also be a target. Therefore, with this application I have three main concerns:

- The safety of those using the Automatic Teller Machine (ATM)
- The safety of those replenishing the ATM
- The security of the ATM itself

The ATM is to be set within the glazing to the right of the front door (when viewed from the outside). There is some natural surveillance of the ATM from the public highway. To provide for the safety of those using the ATM I recommend:

1. Closed Circuit Television (CCTV) cameras are deployed to provide images of those using the ATM and the area about the ATM.
2. An appropriate level of lighting is provided about the ATM, it is unlikely that the light provided by the nearby lamp columns will provide sufficient light. The lighting should work in conjunction with the CCTV system.

The ATM is easily accessible from the road. To provide for the security of the ATM itself I recommend:

1. The ATM should be secured to the floor slab using a recognised fixing system, as outlined within the ATM Security Working Group Best Practice

Guidance, there is no information relating to this in the documentation provided

2. The installation of a monitored alarm system with appropriate sensors to detect early signs of an attack to premises and to the ATM
3. The installation of bollards to PAS68 standard on the public highway to frustrate a ram raid type attack

From the plans supplied it appears that replenishment will take place from within the takeaway. Details as to the replenishment procedures are not provided within the application. However, to provide for the safety of those replenishing the ATM and those within the takeaway should it be open when replenishment occurs, I recommend:

1. The replenishment procedures outlined with the ATM Security Working Group Best Practice Guidance are followed.
2. The installation of CCTV cameras to provide images of the rear of the ATM.
3. The installation of a monitored alarm with a panic button for use by those replenishing the ATM

If I can be of any further assistance please do not hesitate to contact me.

Yours sincerely,

S York
Crime Prevention Design Advisor

DISCLAIMER

This survey is based on information supplied by yourself and the current crime trends. I can only give a view on what measures might reduce the risk of crime and there can be no guarantee that the measures will prevent crime. The advice is given free with no intention of creating a contract. Neither the Home Office or the Police and Crime Commissioner for Hampshire take any other legal responsibility for the advice given.