

Tree Survey Schedule



Site: 22 Manor Close, Havant

T: 07867 725238

Date of site visit: 03.11.2017

E: info@woodsidetrees.co.uk

Tree No.	Species	Height (m)	Stem Diameters (mm)								Branch Spread (m)				Crown Clearance (m)	Height & direction of 1st signif. limb	Age Class	Physiological Condition	Structural Condition	Preliminary Management Recommendations	Est. Remaining Contribution (yrs)	BS5837 Category Rating	Root Protection Radius (m)	RPA (m²)
			Single Stem	2-5 stems					5> stems		N	E	S	W										
				Stem 1	stem 2	stem 3	stem 4	stem 5	Mean Dia.	No. Stems														
1	False acacia	8	510								6	6	6	5	3	2S	M	F	Prominent corner feature, some deadwood, good existing clearance over access.		20-40	B1	6.12	117.7
2	Ash	7	140								3	1	2	3	2	-	Y	P	Weak growth, poor form & no amenity value, self set off-site tree.		10-20	C2	1.68	8.9
3	Elder	5	210								3	1	2	2	3	-	M	P	Weak growth within car port & through roof, heavily asymmetrical, decay cavities & no amenity value.	Fell.	<10	U		
G1	Sycamore, Prunus	9	max. 220								3	5	3	3	2	3E	SM	P	Poor form and structurally weak growth, growing with other boundary shrubs, ivy clad & deadwood.		10-20	C2	2.64	21.9
4	Sycamore	8	230								3	3	3	2	3.5	2.5W	SM	F	Small rear garden tree with little wider amenity value, ivy clad into crown.		10-20	C2	2.76	23.9
5	Eucalyptus	12	550								7	6	3	6	4	2.5W	M	F	Large garden feature, poor form and heavily asymmetrical crown, deadwood.		10-20	C1	6.6	136.8
6	Pittosporum	8		200	150	140	90				3	3	3	3	2	-	EM	F	Large multi stem garden shrub, little wider amenity value.		10-20	C2	3.6	40.8
7	Sweet chestnut	10		330	300						3	4	4	4	2	2N	SM	F	Twin stem boundary tree, previously reduced with dense outer canopy regrowth, main fork with bark inclusion, damage to boundary fence.		10-20	C2	5.4	90