



EXISTING OUTFALL AT
APPROXIMATELY
CHAINAGE 150. SEE
NOTE 9.

BETWEEN CHAINAGE 0 TO 194 SCHEME
DESIGN FOLLOWS THE MAIN SCHEME
DESIGN FOR FRONTAGE 1B. REFER TO
LANG-ACM-ZZ-F1B-DR-ZZ-011701 AND
#051706.

BETWEEN CHAINAGE 194 TO 377 THERE ARE
TIERED OPTIONS FOR REMEDIAL WORKS TO
THE EXISTING SEA WALL. SEE NOTE 8.

EXISTING OUTFALL AT
APPROXIMATELY
CHAINAGE 255. SEE
NOTE 9.

2 No. EXISTING OUTFALLS AT
APPROXIMATELY CHAINAGE
310. SEE NOTE 9.

EXISTING OUTFALL
AT APPROXIMATELY
CHAINAGE 295. SEE
NOTE 9.

FRONTAGE 1B
TO TIE-IN WITH
FRONTAGE 2