

The windows that are to be replaced are painted hardwood sash windows. The two windows are being replaced with an identical product.