


Site Sinah Lane Site, Hayling Island, Hampshire

Client BDW Southampton



	BH 2	BH 6	BH 9	BH 11	BH 14	BH 16		Tide Status
09/10/2017	1.79	2.52	1.62	1.66	1.35	0.89		NR
03/11/2017	1.62	2.41	1.62	1.66	1.21	0.92		NR
07/12/2017	1.59	2.23	1.62	1.67	1.11	1.10		NR
10/01/2018	0.48	1.13	1.16	1.00	0.82	0.40		low
06/02/2018	0.52	1.13	1.22	1.00	0.89	0.52		high
05/03/2018	0.45	1.13	1.18	1.09	0.91	0.43		low
14/11/2018	1.21	1.67	1.43	1.12	replaced	0.91		low
14/12/2018	1.01	1.52	1.22	1.03	destroyed	0.75		low
12/12/2018	destroyed	1.52	1.18	0.90		0.62		high
16/01/2019		1.44	1.11	0.80		0.46		high
19/02/2019		1.21	1.06	destroyed		0.32		low
20/03/2019		1.18	1.00			0.30		low
03/11/2020	replaced	replaced	1.17	replaced	replaced	0.23		high
23/11/2020	destroyed	1.12	1.26	0.32	destroyed	0.16		low
21/12/2020		destroyed	1.21	0.30		0.22		low
19/01/2021			0.95	0.20		0.10		high
15/02/2021			0.74	0.22		0.24	BH A	high
09/03/2021	replaced	replaced	0.30	replaced	replaced	replaced	installed	high
26/10/2021	0.72	0.57	0.35	0.50	0.82	0.61	0.20	high
17/11/2021	0.69	0.57	0.35	0.51	0.82	0.60	0.22	low

Note that tidal status has been assessed from the tidal condition observed at Langstone Bridge