

From: Driver, Jonathan <Jonathan.Driver@havant.gov.uk>

Sent: 06 May 2022 18:27

To: Eaves, David <David.Eaves@havant.gov.uk>

Subject: RE: APP/21/00200 32 New Lane, Havant - Drainage Conditions & others outstanding Conditions 15 and 16

Hi David,

I've looked at the comments, schedule, and again at C200810-PIN-XX-XX-DR-C-00205 P13. I've also looked up manufacturer specification info. for popular models of bypass interceptor. It would appear that flows at the interceptor units will be allowed to exceed the nominal flows listed on the ...-00205 P13 drawing, but also that products sized to the nominal flows are recommended for catchment areas which exceed those proposed to be served by a comfortable margin. It would be very unlucky for a significant spill to occur under exceedance flow conditions (where bypass is active), and Fellows planning makes a good point Re: the purpose of the bypass in avoiding washout of retained pollutants.

Given the clarifications, and the assurance in respect of maintenance being in accordance with the quoted guidance; I see no reason to object to the discharge of either c.15 or c.16 on pollution grounds.

Best Regards,

Jon

Jonathan Driver

Environmental Control Officer