

This is the image of the original farmhouse plate rack which I have asked to be in documents. Please can this be added with the following text.

Seafield original farmhouse plate rack circa 1816 on the Little Seafield side of the new proposed log burner siting.



The glass is slipping out of the wood frame and debris is collecting in the gutter. There should be a 430mm clearance. There will need to be 430mm clearance on both the Conservatory gutter and roof gutter in the new proposed flue installation

