

Further to your email below I have spoken to our clients on site and they have confirmed the following:

- The temporary tree protection will be reinstated in accordance with the Tree Protection plan.
- The land drain to the rear of plots 1 & 2 was required to address a small localized problem in the corner of the boundary, there is no intention or requirement to extend this drain any further.
- They are aware and confirmed that there will be no burning on site.

Please come back to me should you require any further confirmation.

Kind regards