

12 AUG 2016



Original level view



Original level view



Raised level view



Raised level view



Weep holes



Timber Tie Back System

Concrete base foundations

