

They showed their SUDs system (such as it is) with an overflow into the sewerage system (due to ground conditions). As long as SW are happy that there is capacity in the system then that is OK. The developer should have asked by now for a capacity check from SW anyway.

Best wishes

Steve Mountain
Project Engineer
Transport & Implementation Team
Environment & Neighbourhood Quality
Havant Borough Council
Southmoor Offices and Depot, 2 Penner Road, Havant, PO9 1QH
[\[Location Map\]](#) [\[Get here by bike \(journey planner\)\]](#) [\[Get here by public transport \(journey planner\)\]](#) [\[Why not Car Share?\]](#)