




INTERNAL VIEWS OF EXISTING ROOF LIGHTS



AERIAL VIEW NEW INSTALLATION APPROX 1967



EXTERNAL VIEWS OF ROOFLIGHTS SHOWING PERISHED CONDITIONS.

CURRENT AERIAL VIEW

