

IM/LN/10140A

13th October 1999

Mr.D.Lamonby
Thicket House
6 The Thicket
Widley
Waterlooville
PO7 5JL

Dear Sir

Re: Connection of the Foul Water Pipe: Thicket House, Widley

With reference to the above repair of drainage system, I have pleasure submitting my report.

The works involved taking a drain away from the waste down pipe around the wall via a new inspection chamber, which was installed under one of the paving slabs so as not to be intrusive. A connection pipe was then laid through the gate and along the drive to connect into inspection chamber F3, a total length of 17 metres.

Details of the works carried out:

Carefully excavated a trench line on the route as indicated above.
Cut back and remove root system from nearby Redwood tree which had penetrated and displaced original drainage system.
Supply and lay 100mm UPVC pipework on a pea shingle bed and surround.
Connect up the new pipework.
Backfill with suitable excavated material and remove any surplus spoil off site.
Reinstate all disturbed surfaces and leave the site in a tidy condition.

Our invoice IM/LN/10140A 6th October 1999 applies.

Please note, our workmanship and all material used in the completion of this work is covered by a 12 month written guarantee.

Yours faithfully

I.Miller, B Eng (Hons)
Contracts Manager



**Water Management
NETWORK**



WHITE HORSE

THE COMPLETE DRAINAGE COMPANY

White Horse Maintenance Limited, Old Brickyard Road,
Sandleheath, Fordingbridge, Hampshire SP6 1PA
Tel: 01425 656116 Fax: 01425 657563



Directors: M.A. Jackson B.A. F.F.A. M.I.M. & M.C.I.M. C.A. Jackson R.J. Peple
K.E. Wood
Registered in England No. 1776008