

PEP Project Management Ltd

1. To be read in conjunction with other consultants drawings;
2. Check site conditions prior to commencement of work;
3. Any discrepancies to be reported directly to the Project Manager;
4. Do not scale off drawing. Use figured dimensions only;
5. All dimensions for existing buildings and openings to be checked on site