




HAVANT BOROUGH COUNCIL
DEVELOPMENT CONTROL

24 MAY 2012

VELUX®

ECX-TF




RECEIVED



0°-30°









VAS 451535-2012-01






HAVANT BOROUGH COUNCIL
DEVELOPMENT CONTROL
24 MAY 2012
RECEIVED

1a





			
	W mm	H mm	X mm
ECX C02	600	900	479
ECX C04	600	1000	543
ECX F06	700	1200	606
ECX M04	800	1000	543
ECX M06	800	1200	606
ECX M08	800	1400	676
ECX P04	1000	1000	543
ECX P10	1000	1500	740
ECX S06	1200	1200	606
ECX U04	1400	1000	543
ECX U08	1400	1400	676
ECX U10	1400	1500	740







	W mm	H mm	X mm
ECX C02	600	940	479
ECX C04	600	1150	543
ECX F06	700	1360	606
ECX M04	800	1150	543
ECX M06	800	1360	606
ECX M08	800	1590	676
ECX P04	1000	1150	543
ECX P10	1000	1810	740
ECX S06	1200	1360	606
ECX U04	1400	1150	543
ECX U08	1400	1590	676
ECX U10	1400	1810	740

1c





HAVANT BOROUGH COUNCIL
DEVELOPMENT CONTROL
24 MAY 2012
RECEIVED





			
	W mm	H mm	X mm
ECX C02	600	940	479
ECX C04	600	1150	543
ECX F06	700	1360	606
ECX M04	800	1150	543
ECX M06	800	1360	606
ECX M08	800	1590	676
ECX P04	1000	1150	543
ECX P10	1000	1810	740
ECX S06	1200	1360	606
ECX U04	1400	1150	543
ECX U08	1400	1590	676
ECX U10	1400	1810	740




2




3






4






5








6








7







8







9



HAVANT BOROUGH COUNCIL
DEVELOPMENT CONTROL
24 MAY 2012
RECEIVED








HAVANT BOROUGH COUNCIL
DEVELOPMENT CONTROL





24 MAY 2012

RECEIVED

14



15





AR: VELUX Argentina S.A.
3488 639944 / 45 / 46
AT: VELUX Österreich GmbH
02245/32 3 50
AU: VELUX Australia Pty. Ltd.
1300 859 856
BA: VELUX Bosna i Hercegovina d.o.o.
033/626 493, 626 494
BE: VELUX Belgium
(010) 42.09.09
BG: VELUX Bulgaria EOOD
02/955 99 30
BY: FE VELUX Roof Windows
(017) 217 7385
CA: VELUX Canada Inc.
1 800 88-VELUX (888-3589)
CH: VELUX Schweiz AG
0848 945 549
CL: VELUX Chile Limitada
2 953 6789
CN: VELUX (CHINA) CO. LTD.
0316-607 27 27
CZ: VELUX Česká republika, s.r.o.
531 015 511
DE: VELUX Deutschland GmbH
0180-333 33 99
DK: VELUX Danmark A/S
45 16 45 16

EE: VELUX Eesti OÜ
621 7790
ES: VELUX Spain, S.A.
91 509 71 00
FI: VELUX Suomi Oy
0207 290 800
FR: VELUX France
0821 02 15 15
0,119€ TTC/min
GB: VELUX Company Ltd.
01592 778 225
HR: VELUX Hrvatska d.o.o.
01/5555 444
HU: VELUX Magyarország Kft.
(06/1) 436-0601
IE: VELUX Company Ltd.
01 848 8775
IT: VELUX Italia s.p.a.
045/6173666
JP: VELUX-Japan Ltd.
0570-00-8145
LT: VELUX Lietuva, UAB
(85) 270 91 01
LV: VELUX Latvia SIA
67 27 77 33
NL: VELUX Nederland B.V.
030 - 6 629 629
NO: VELUX Norge AS
22 51 06 00

NZ: VELUX New Zealand Ltd.
0800 650 445
PL: VELUX Polska Sp. z o.o.
(022) 33 77 000 / 33 77 070
PT: VELUX Portugal, Lda
21 880 00 60
RO: VELUX România S.R.L.
0-8008-83589
RS: VELUX Srbija d.o.o.
011 20 57 500
RU: ZAO VELUX
(495) 737 75 20
SE: VELUX Svenska AB
042/20 83 80
SI: VELUX Slovenija d.o.o.
01 724 68 68
SK: VELUX Slovensko, s.r.o.
(02) 33 000 555
TR: VELUX Çatı Pencereleri
Ticaret Limited Şirketi
0 216 302 54 10
UA: VELUX Ukraina TOV
(044) 2916070
US: VELUX America Inc.
1-800-88-VELUX

www.velux.com

dwel| design

24 MAY 2012

RECEIVED

15/06/2011
15/06/2011
04/07/2011
05/09/2011
19/09/2011
19/09/2011
17/05/2012
21/05/2012

[illegible]

