

Supporting Document Summary

Proposal Name West Stoke House - North wall repairs

Reference 14353750

Version Number 1

Submission Date 23-Sep-2025

Submitted Items 13

To be sent by post

This contains the following 1 document(s).

Document Type The location plan
Status New
Document Description

File Name: Secil NHL 5 Datasheet.pdf

File Type application/pdf
File Size (bytes) 321396

This contains the following 1 document(s).

Document Type Other relevant information
Status New
Document Description Datasheet for NHL5 Mortar

File Name: HERITAGE STATEMENT.docx

File Type application/vnd.openxmlformats-officedocument.wordprocessingml.document
File Size (bytes) 16963

This contains the following 1 document(s).

Document Type Heritage statement
Status New
Document Description Heritage Statement

File Name: WSH Plan.pdf

File Type application/pdf

File Size (bytes) 549254

This contains the following 1 document(s).

Document Type Block plan of the site

Status New

Document Description Site Plan

File Name: Plan Elevation WSH Repairs-2.pdf

File Type application/pdf

File Size (bytes) 78500

This contains the following 1 document(s).

Document Type Elevation (Front) - Existing

Status New

Document Description Rough sketch of the current north elevation to identify window being replaced and section of wall to be rendered.

File Name: WSH Design and Access Statement - North Wall Repairs.docx

File Type application/vnd.openxmlformats-officedocument.wordprocessingml.document

File Size (bytes) 14580

This contains the following 1 document(s).

Document Type Design and access statement

Status New

Document Description Design & Access Statement

File Name: West Stoke House Render Sample.pdf

File Type application/pdf

File Size (bytes) 342903

This contains the following 1 document(s).

Document Type Other relevant information

Status New

Document Description Report from Lime Centre to identify render mix.

File Name: West Stoke House Window TDplan.pdf

File Type application/pdf

File Size (bytes) 150434

This contains the following 1 document(s).

Document Type Other relevant information

Status New

Document Description Technical drawing of the replacement window (plan view)

File Name: West Stoke House Window TDside.pdf

File Type application/pdf

File Size (bytes) 120779

This contains the following 1 document(s).

Document Type Other relevant information

Status New

Document Description Technical drawing of the replacement window (side view)

File Name: IMG_0762.jpeg

File Type image/jpeg

File Size (bytes) 477159

This contains the following 1 document(s).

Document Type Photographs and photomontages

Status New

Document Description Photograph of damaged wall and window

File Name: IMG_0758.jpeg

File Type image/jpeg

File Size (bytes) 464763

This contains the following 1 document(s).

Document Type Photographs and photomontages

Status New

Document Description Photograph of damaged wall and window2

File Name: IMG_0756.jpeg

File Type image/jpeg

File Size (bytes) 393566

This contains the following 1 document(s).

Document Type Photographs and photomontages

Status New

Document Description Photograph of damaged wall and window3

File Name: IMG_0765.jpeg

File Type image/jpeg

File Size (bytes) 374546

This contains the following 1 document(s).

Document Type Photographs and photomontages

Status New

Document Description Photograph of damaged wall and window4