

MR. G. SPELLER
REF APP/21/01035

15/10/21

Re 8 WARFIELD CRESCENT.

Dear Sir,

My only comment is that the new extension projects above the roof line, & thus looks like what it is - stuck on the back.

In my ~~opinion~~ opinion either the extension needs lowering, or else the roof pitch needs changing to come above the extension.

yours sincerely

