





Woodwork rotten
Will require repairing



Top columns are peeling
Will require repainting