

Mr and Mrs duke
37, Horndean Road
Emsworth
Portsmouth
PO10 7UP

Atworth Arboriculture Ltd

189, Purlpit
Atworth
Melksham
Wiltshire
SN12 8HJ

Phone: 01225 708508
Mobile: 07970 467918
vincentcainey@yahoo.co.uk

BS5837:2012 Assessment

37, Horndean Road BS5837 (2012), Tree survey

Tree ID : T1				Tag :				Assessor : Vince Cainey				Bats :									
Species : Atlas Cedar <i>Cedrus atlantica</i>				TPO :				Inspected : 14 January 2026				Cons Area : No									
								Next Insp : Not Required													
								1st Branch:													
-----Stems-----				-----Health-----				-----RP-----				-----Clearance (m)-----				-----Spread (m)-----					
H (m)	No	Ø (mm)	Maturity	Crown	Stem	Basal	Phy Con	Cat	ERC	A (m²)	R (m)	Site Status	Priority	N	E	S	W	N	E	S	W
14	1	720	Mature	Poor	Poor	Good	Fair	C	<20yrs	234.5	8.63	Pre Construction		4	4	4	4	4	6	6	7
Survey Comment : Next to entrance and Horndean Road. Dense ivy up stem and into the crown, suspect ring bark on stem. Crown condition poor with die back																					
Tree Comment :																					

Tree ID : T2				Tag :				Assessor : Vince Cainey				Bats :									
Species : Common Lime <i>Tilia europaea</i>				TPO :				Inspected : 14 January 2026				Cons Area : No									
								Next Insp : Not Required													
								1st Branch:													
-----Stems-----				-----Health-----				-----RP-----				-----Clearance (m)-----				-----Spread (m)-----					
H (m)	No	Ø (mm)	Maturity	Crown	Stem	Basal	Phy Con	Cat	ERC	A (m²)	R (m)	Site Status	Priority	N	E	S	W	N	E	S	W
17	1	740	Mature	Good	Fair	Fair	Fair	B	>40 yrs	247.8	8.88	Pre Construction		3	3	3	3	6	6	3	6
Survey Comment : This tree is adjacent to T1. Some light Ivy on stem, This tree also ring barked. Some hanging dead wood to the northeast over the footpath.																					
Tree Comment :																					

BS5837:2012 Assessment

Tree ID : T3

Species : Laurel

Tag :

TPO :

Assessor : Vince Cainey

Inspected : 14 January 2026

Next Insp : Not Required

1st Branch:

Bats :

Cons Area : No

Stems			Health					RP		Clearance (m)				Spread (m)			
H (m)	No	Eq Ø (mm)	Maturity	Crown	Stem	Basal	Phy Con	Cat	ERC	A (m²)	R (m)	Site Status	Priority	N	E	S	W
7	3	358		Good	Fair	Fair	Fair	C	>40 yrs	58.1	4.3	Pre Construction		2	2	2	2

Survey Comment : Portuguese Laurel in neighbours garden but close to drive

Tree Comment :