
RILEY LARKIN Limited

LEVEL MONITORING - DISTORTION SURVEY READINGS

Provider Details		Client Details		Risk Address	
Name:	MHN Ltd	Insurance Co.:	Nationwide	Occupier:	Mrs K Pouralli
		Client Name:	Riley Larkin	Address:	22 Oakmont Drive
		Contact:	Eamon Larkin	Address:	Waterlooville
Date of Issue:	10/2/11	Email:	alistair@rileylarkin.co.uk	Town:	
		Client Ref:	NA100336RL	County:	Hampshire
Monitoring Details		Address:	Hadleigh House	Post Code:	PO8 8TH
Instruction Date:	4/8/10	Address:	96 High Street	Tel Home:	02392 345 220
First Reading Date:	17/08/2010	Town:	Bushey	Tel Work:	
Maximum No Visits:	7	County:	Hertfordshire	Mobile:	
Anticipated Expiry Date:	Sep 2010	Post Code:	WD23 3HB	Other:	
Monitoring Int (Wks):	8 weekly	Other Email:		Other:	

			Target Date:												
			Reading Date:	17/8/10	18/10/10	13/12/10	9/2/11								
			Issue Date:	18/8/10	19/10/10	15/12/10	10/2/11								
Row No.	**Point Name**	**X Co-ordinate**	**Y Co-ordinate**	**1**	**2**	**3**	**4**	**5**	**6**	**7**	**8**	**9**	**10**	**11**	**12**
1	1	0.00	0.00	10.0170	10.0173	10.0168	10.0171								
2	2	-3.20	0.00	10.0047	10.0048	10.0047	10.0050								
3	3	-6.30	0.00	10.0000	10.0000	10.0000	10.0000								
4		-6.30	1.20												
5	4	-12.00	1.20	10.0031	10.0040	10.0043	10.0041								
6	5	-12.00	8.90	9.9785	9.9797	9.9800	9.9805								
7	6	-9.00	8.90	9.9675	9.9687	9.9693	9.9695								
8	7	-6.00	8.90	9.9629	9.9669	9.9697	9.9707								
9	8	-3.60	8.90	9.9575	9.9628	9.9670	9.9687								
10		-3.00	8.90												
11	9	-2.60	9.30	9.9570	9.9658	9.9719	9.9729								
12	10	-1.80	9.80	9.9516	9.9633	9.9706	9.9731								
13	11	-0.80	9.30	9.9539	9.9647	9.9727	9.9747								
14		-0.40	8.90												
15	12	0.00	8.90	9.9499	9.9600	9.9660	9.9681								
16	13	0.00	8.00	9.9636	9.9670	9.9708	9.9722								
17	14	0.00	4.50	9.9835	9.9845	9.9856	9.9860								
18		0.00	0.00												
19															
20															
21															
22															
23															
24															
25															
26															
27															
28															
29															
30															
31															
32															

REAR



DATUM = STATION 3

FRONT

HAVANT BOROUGH COUNCIL
09 MAY 2011
RECEIVED


- 09/02/2011 The Occupier was not unduly worried
- All stations have been installed within the same brick course. There fore initial readings can be interpreted as Distortion Data
- Further readings to be taken in Apr '11

RILEY LARKIN Limited

LEVEL MONITORING - DISTORTION MOVEMENT SKETCH

Client: Riley Larkin

Client Ref: NA100336RL



Datum Reading
Reading 1 (17/8/10)
Reading 2 (18/10/10)
Reading 3 (13/12/10)
Reading 4 (9/2/11)
Reading 5 (0/1/00)
Reading 6 (0/1/00)
Reading 7 (0/1/00)
Reading 8 (0/1/00)
Reading 9 (0/1/00)
Reading 10 (0/1/00)
Reading 11 (0/1/00)
Reading 12 (0/1/00)

HAVANT BOROUGH COUNCIL
RECEIVED
09 MAY 2011

Notes:
Vertical distorted scale 1: 20


Point labels give level difference of last reading from original datum in mm.

RILEY LARKIN Limited

LEVEL MONITORING - DISTORTION SURVEY READINGS

Client: Riley Larkin **Client Ref:** NA100336RL **Chart Scale 1:1000**


1




2



3



HAVANT BOROUGH COUNCIL
09 MAY 2011
RECEIVED



READINGS IN (mm)	JUL'10	AUG	SEPT	OCT	NOV	DEC	JAN'11	FEB	MAR
CRACK 1 / A-B	64.89		63.38		61.77		61.7		61.68
CRACK 2 / A-B	72.13		71.28		69.69		69.15		69.09
CRACK 3 / A-B	51.98		51.33		49.19		48.64		48.59
CRACK 4 / A-B	64.48		61.12		59.37		59.03		58.99
CRACK 4 / B-C	57.26		54.13		52.04		51.44		51.33
CRACK 4 / A-C	90.84		90.14		90.19		90.17		90.17
CRACK 5 / A-C	70.52		70.11		68.97		68.11		67.99
CRACK 5 / B-C	63.83		63.27		61.36		60.25		60.06
CRACK 5 / A-B	93.7		93.16		93.12		93.36		93.23

CRACK 1 / A-B	LOCATION : - SIDE OF REAR BAY - HIGH LEVEL	MAX-MIN (mm)=	3.21
CRACK 2 / A-B	LOCATION : - LHS OF REAR BAY - LOW LEVEL	MAX-MIN (mm)=	3.04
CRACK 3 / A-B	LOCATION : - REAR RH CORNER	MAX-MIN (mm)=	3.39
CRACK 4 / A-B	LOCATION : - REAR RH CORNER - LOW LEVEL - VERTICAL	MAX-MIN (mm)=	5.49
CRACK 4 / B-C	LOCATION : - HORIZONTAL	MAX-MIN (mm)=	5.93
CRACK 4 / A-C	LOCATION : - DIAGONAL	MAX-MIN (mm)=	0.7
CRACK 5 / A-C	LOCATION : - ABOVE WINDOW TO RH ELE - HORI	MAX-MIN (mm)=	2.53
CRACK 5 / B-C	LOCATION : - VERTICAL	MAX-MIN (mm)=	3.77
CRACK 5 / A-B	LOCATION : - DIAGONAL	MAX-MIN (mm)=	0.58


MONITORING DATA FROM : -
22 OAKMOUNT DRIVE
WATERLOOVILLE
HAMPSHIRE
PO8 8TH
CLIENT : - MRS K POURALLI
DATE : - 09/Mar/2011
JOB NO.:- 100336

COMMENTS.

SHEET 1 OF 2

EXTERNAL
MB

HAVANT BOROUGH COUNCIL
09 MAR 2011
RECEIVED



READINGS IN (mm)	JUL'10	AUG	SEPT	OCT	NOV	DEC	JAN'11	FEB	MAR
CRACK 6 / A-C	73.03		72.51		70.38		69.77		69.66
CRACK 6 / B-C	59.44		58.86		58.58		58.48		58.48
CRACK 6 / A-B	83.63		83.42		83.43		83.44		83.42

CRACK 6 / A-C	LOCATION : - AS 5 - BELOW WINDOW - HORIZONTAL	MAX-MIN (mm)=	3.37
CRACK 6 / B-C	LOCATION : - VERTICAL	MAX-MIN (mm)=	0.96
CRACK 6 / A-B	LOCATION : - DIAGONAL	MAX-MIN (mm)=	0.21

MONITORING DATA FROM : -
22 OAKMOUNT DRIVE
WATERLOOVILLE
HAMPSHIRE
PO8 8TH
CLIENT : - MRS K POURALLI

DATE : - 09/Mar/2011
JOB NO.:- 100336

COMMENTS.

SHEET 2 OF 2

EXTERNAL
MB

RECEIVED
06 MAY 2011
HAVANT BOROUGH COUNCIL